









SET OF THE PARTS




PARTS NOT FOR USE





P



MASKS FOR PAINTING



ASSEMBLY INSTRUCTION




ASSEMBLY INSTRUCTION




4

12
14
15
16
32
33
34
P4 x5




5

13
17
18
19
32
33
34
P4 x5




6

3
5
7
8



7


102
103




ASSEMBLY INSTRUCTION



- 8
- 4
- 6
- 7
- 3
- 4
- 5



- 9
- 8
- 25 x2
- 65
- 68
- 70
- 71
- 74
- 75 x2
- 76 x2
- 82
- 92
- 93
- 94
- 95
- 96
- P1 x2
- P2 x2
- P3 x10



ASSEMBLY INSTRUCTION



10

9

30 x2

35 x2

69

73

77

79

81

83


85

86

97

99

104



11

10

29 x2

36 x2

40 x4

41

42 x2

45

47

48

49

50


60 x2

61

62

64

91



MARKING & PAINTING

HFB-320/ECM Hansa Jet

