






БМ-21 «Град»
Реактивная система
залпового огня

ICM
1:72

BM-21 «Grad»
Multiple Launch
Rocket System



x2

СДЕЛАТЬ 2 ДЕТАЛИ
MAKE 2 PCS



ОТРЕЗАТЬ
REMOVE




НЕ КЛЕИТЬ
DO NOT CEMENT




ПРИ СБОРКЕ НЕ ИСПОЛЬЗУЕТСЯ
PARTS NOT FOR USE



ПРОИЗВОЛЬНЫЙ ВЫБОР
OPTIONAL





Стандартная окраска БМ-21 «Град»
Standart painting scheme of BM-21 «Grad»

	Model Master			Model Master		
A	1749	Черный, матовый	Flat White	F	1527	Оранжевый, гляцевый
B	1597	Черный, полуматовый	Semigloss Black	G	1701	Коричневый
C	1712	Зеленый, матовый	Field Green	H	1785	Ржавчина
D	1790	Серебряный хром	Chrome Silver	J	1735	Дерево
E	1590	Красный, гляцевый	Fire Red	K	1780	Сталь

ВНИМАНИЕ!

Работать с клеем и красками в проветриваемом помещении и не допускать открытого огня. Для сборки модели рекомендуется применять полистирольный клей ПС или его зарубежные аналоги. Отделяя детали от литников, используйте модельный нож для зачистки.

Метод нанесения аппликаций

Чистым ножом или ножницами аккуратно вырежьте необходимую аппликацию.

Вырезанную аппликацию погрузите в теплую воду на 20 секунд.

Приложив аппликацию к необходимому месту, аккуратно удалите подложку.

Марлевым тампоном удалите пузырьки воздуха и слегка прижмите аппликацию.

После высыхания аппликаций влажным тампоном удалите остатки клея вокруг них.

CAUTION!

When you use glue or paint, do not use near open flame, and use in well ventilated room.

Glue and paint are not included.

When you take parts off from the runner frame, use a modeling scissors and trim excess plastic with a cutter or a file.

Correct Method for Applying Decals

Clean model surface with wet cloth.

Cut each design out of decal sheet and dip them in warm water for 20 seconds.

Check with finger tip if design is loose on base paper. If so, place it on proper position on model and slide off base paper leaving design on model.

Move design to exact position with wet finger tip, and push out excess water and air bubbles under decal with soft cotton cloth.

When decals get dry, wipe off with wet cloth excess glue left around decals.

ООО "ICM Холдинг"
Украина, 01033, Киев-033, а/я 59
Тел./факс (+38044) 494-04-04

E-mail: icm@icm.com.ua, www.icm.com.ua

"ICM Holding"
P.O. 59, Kyiv, 01033, Ukraine,
Tel./fax (+38044) 494-04-04